





































































































WHEEL HUB		Dimension(mm)			PICTURE	APPLICATION
REFER NO.	d	F	B			
DACF1083CR(KOYO)	30	117	37		FIAT	
BAFB633807D(SKF)	30	117	37		FIAT	
DACF1083CR(KOYO)	30	117	37		FIAT	
DACF1083CR-1(KOYO)	30	117	37		FIAT	
633622-1	30	116	37		FIAT	
633622	30	117	37		FIAT	
633622-2	30	116	37		FIAT	
633622-3	30	116	37		FIAT	
TGB12095S43(SNR)	25	132.5	43		RENAULT	
TGB12095S49(SNR)	25	132.5	43		RENAULT	
TKR8645 YJ	25	132.5	43		RENAULT	
IR-8688	32	129	38		PEUGEOT	
800179A不压齿圈	30	120	37	without ABS	VW	
800179D(FAG)	30	120	37		VW	
801191E(FAG)	28	120	39		VW	
801191AD压磁性圈	28	120	39		VW	

















	35016	28	120	40		
	28BWK15(NSK)	28	120	40		SUZUKI
	DACF1050B(KOYO)	28	125.5	48		MITSUBISHI
	28BWK08g(NSK)	28	125.5	48		MITSUBISHI
	57210-25000(OE)	28	140	38		KIA
	57210-25100(OE)	28	140	38		KIA
	52710-2D000(OE)	32	139	45		HYUNDAI
	52710-2D115(OE)	32	139	45		HYUNDAI
	52710-29XXX(OE)	28	139	38		HYUNDAI
	52710-29450(OE)	28	139	38		HYUNDAI
	52710-29671(OE)	28	139	38		HYUNDAI
	52710-22400(OE)	28	139	38		HYUNDAI
	52710-22500(OE)	28	139	38		HYUNDAI
	52710-29400(OE)	28	139	38		HYUNDAI
	512165(BCA)	28	139	38		HYUNDAI
	DACF310203	31	—	47		HYUNDAI
	513202(BCA)	37	151.8	52		FORD
	578413(FAG)	37	138.8	45		BMW



















580494(FAG)	45	—	41		BMW
3502950	30	123	50		哈飞赛马
BAF0006D不压齿圈	30	122	46	without ABS	KIA
BAF0006D(SKF)	30	122	46		KIA
BAF0013E(SKF)	30	116.5	37		FIAT
BAF0013AD(SKF)	30	116.5	37		FIAT
DAF20023	37	151	52		FORD
IR-8683不压齿圈	30	120	37	without ABS	VW
BAF-4104E(SKF)	30	120	37		VW
BAF-0095B(SKF)	30	120	37		VW
DACF1005C(KOYO)	31	120	40		BMW
DACF1005CABS	31	120	40		BMW
DACF1018L(KOYO)	35	137	45		OPEL
DACF1033K(KOYO)	37	139	45		BMW
DACF1033K-1(KOYO)	37	139	45		BMW
DACF1033K-2(KOYO)	37	139	45		BMW
DACF1091(KOYO)	30	—	50		MITSUBISHI、 中华
DACF1092(KOYO)	40	—	43		MITSUBISHI、 中华

















DACF1097(KOYO)	30	—	42		TOYOTA
28BWK12(NSK)	28	—	42		TOYOTA
HUB065/15(NTN)	28	134	40		SUZUKI
HUB081-44(NTN)	43	—	44		HONDA
HUB083-15(NTN)	30	151.5	41		HONDA
HUB083-15ABS	30	151.5	41		HONDA
HUB008(NTN)	28	134	40		HONDA
HUB008-72(NTN)	28	134	40		HONDA
HUB005-39(NTN)	30	136	41		HONDA
HUB005-39ABS	30	136	41		HONDA
HUB184(NTN)	27	134	50		NISSAN
HUB184ABS	27	134	50		NISSAN
(N16) HUB184	27	148	50		NISSAN
(N16) HUB184ABS	27	148	50		NISSAN
HUB188-6(NTN)	30	148	48		NISSAN
HUB188-6ABS(46齿)	30	148	48		NISSAN
HUB188-4ABS(44齿)	30	148	48		NISSAN
HUB280(NTN)	30	140	50		



















HUB280-1(NTN)	30	140	50		
W135007ABS	30	140	50		
TGB12894(SNR)	32	128	34		RENAULT
TKR8592 YJ	32	128	34		RENAULT
TKR8592 YJ	32	128	34		RENAULT
27BWK03(NSK)	27	148	55		NISSAN
27BWK03	27	148	55		NISSAN
30BWK10(NSK)	30	—	42		TOYOTA
DACF1041不压齿圈	30	122	47	without ABS	MAZDA
DACF1041JR(KOYO)	30	122	47		MAZDA
HUB048-35(NTN)	27	134	40		VW
HUB048-35(NTN)	27	134	40		VW
HUB042-32(NTN)	30	148	48		NISSAN
800179B(FAG)	30	120	37		VW
36BWK02(NSK)	36	140	62		MAZDA
DACF1050B JH	28	125.5	48		MITSUBISHI
BAF0066D(SKF)	32	128	38		PEUGEOT
HUB002(NTN)	25	134	40		HONDA

DACF1086(KOYO)	30	140	50		
BAF-4093B(SKF)	30	140	50		
DACF1086-2(KOYO)	30	140	50		
KY2058多一个小孔	30	140	50		
DACF1023D(KOYO)	35	137	45		VOLVO
DACF1023D	35	137	45		VOLVO
HUB294(NTN)	28	134	45		HONDA
512025(BCA)	27	125	51.5		NISSAN
BE00700	30	116.5	37		FIAT
BE00700(5孔)	30	116.5	37	FIVE HOLES	FIAT
28BWK06(NSK)	28	148	48		CHARADE
TGB40175S05(SNR)	32	129	38		PEUGEOT、 CITROEN
IR-8609	32	129	38		PEUGEOT、 CITROEN
TGB40175S06(SNR)	32	129	38		PEUGEOT、 CITROEN
39040403	32	129	38		PEUGEOT、 CITROEN
BAF4047D(SKF)	33	140	51		VOLVO
30BWK06(NSK)	30	148	48		NISSAN
HUB066-52(NTN)	33	139.5	51	without ABS	MAZDA










HUB066-53(NTN)	33	139.5	51		MAZDA
BAF-0058 B(SKF)	28	120	39		VW
52710-34501(OE)	34	139	42		HYUNDAI
52710-34700(OE)	34	139	42		HYUNDAI
DACF1085(KOYO)	30	140	50		MITSUBISHI
DACF1085(KOYO)	30	140	50		
DACF1050B-4	28	125.5	48		MITSUBISHI
HUB030-22 (43BWK01B)	43	—	56		NISSAN
43200-4M400(OE)	27	148	50		NISSAN
XTGB40490(SNR)	30	117	37		FIAT
BAF4048C(SKF)	33	140	51		NISSAN
HUB042(NTN)	30	148	48		NISSAN
DACF1034AR-2	33	140.1	47		MITSUBISHI
DACF1034C-3	33	140.1	47		MITSUBISHI
52710-2D100(OE)	32	139	42		HYUNDAI
HUB254(NTN)	28	130	40		SUZUKI
HUB254-20	28	130	40	with ABS	SUZUKI
801191压轴承	28	120	42		VW

	28BWK19A(NSK)	28	134	45		HONDA
	HUB283-5(NTN)	30	151.5	59		HONDA
	576681EA(FAG)	37	139	45		BMW
	803640CD(FAG)	—	126.5	—		VW
	805201D(FAG)	—	149.5	—		VW
	BAF-0125(SKF)	43/45	—	37		AUDI、VW
	BAF-0127(With ABS)	43/45	—	37		AUDI、VW
	BAF0066C(SKF)	32	128	38		PEUGEOT
	HUB181-22(NTN)	30	151.5	59		HONDA
	512154(BCA)	28	135.4	47		CHRYSLER
	HUB227-26(NTN)	30	139	56		HONDA
	HUB227-26(NTN)	30	139	56		HONDA
	压3464	30	140	37		
	HUB132(NTN)	45	—	49		HONDA
	TGB12894(SNR)	32	128	34		PEUGEOT、CITROEN
	TGB12894 S07(SNR)	32	128	34		PEUGEOT、CITROEN
	HUB249(NTN)	34	146.5	58		HONDA、Odyssey
	TGB12096S41(SNR)	25	133	43		RENAULT

TGB12095S43(SNR)	25	133	43		RENAULT
TGB12095S42(SNR)	25	133	43		RENAULT
TGB12095S49(SNR)	25	133	43		RENAULT
TGB12095S48(SNR)	25	133	43		RENAULT
TKR8569	25	133	43		RENAULT
TKR8637	25	132.5	43		RENAULT
IR-8605	32	128	38		PEUGEOT、 CITROEN
TGB40189S04(SNR)	30	120	52		PEUGEOT、 CITROEN
29040404不压齿圈	35	136	43	without ABS	FORD
29040405	35	136	43		FORD
BE00733	35	116	37		FIAT
580494C(FAG)	45	—	41		BMW
JD03	30	134	41		HONDA、 ROVER
TGB12933不压齿圈	30	133	46	without ABS	RENAULT
TGB12933S01(SNR)	30	133	46		RENAULT
TGB12933S03(SNR)	30	133	46		RENAULT
BE00700	30	120	37		FIAT
29030409	45	—	51		

TKR8574	25	128	34		PEUGEOT、 CITROEN
TKR8578	25	128	34		PEUGEOT、 CITROEN
U-100	30	139	55		DAWOO
512179(BCA)	30	151.8	59		HONDA
51KWH01(NSK)	51	—	55		TOYOTA
BAF0026(SKF)	35	135.8	45		SAAB
BAFB633872(SKF)	30	130.7	43		SAAB
BAFB633903B(SKF)	30	130.7	43		SAAB
PL-6459	30	116.5	37		FIAT
520100(BCA)	—	—	—		FORD
HUB227(BCA)	30	139	56		HONDA
512167(BCA)	28	135	43		CHRYSLER
513050(BCA)	28	134	40		HONDA
BAF0103D(SKF)	30	136	41		
HUB207(NTN)	34	140	53		HONDA
512023(BCA)	28	135.3	40		CHRYSLER
512024(BCA)	35	136	42		FORD
512029(BCA)	32	139.9	38		CHRYSLER

513030(BCA)	30	122	47		FORD
512107(BCA)	31.76	139	52		FORD
512149(BCA)	31.76	139	52		FORD
803199A(FAG)	25	120	37		VW
513115(BCA)	34.5	139	51.5		FORD
803755AA(FAG)	32	131	46		AUDI、VW
HUB294-3	28	134	45		HONDA
54KWH02(NSK)	54	120	59		TOYOYA
35040406(带磁性圈)	25	128	38		PEUGEOT、CITROEN
35040407	25	129	38		PEUGEOT、CITROEN
35040408	25	129	38		PEUGEOT、CITROEN
39040401	25	129	38		PEUGEOT、CITROEN
39040402(带磁性圈)	25	128	38		PEUGEOT、CITROEN
TGB40540S04(SNR)	25	128	38		PEUGEOT、CITROEN
TGB40540S03(SNR)	25	128	38		PEUGEOT、CITROEN
TGB40540S06(SNR)	25	128	38		PEUGEOT、CITROEN
TGB40266S01(SNR)	25	133	46		PEUGEOT、CITROEN
77431795	30	135.5	43		PEUGEOT、CITROEN

805546C(FAG)	—	131.3	—		FORD
BAF-4139C(SKF)	28	120	39		VW
801191BA(FAG)	28	120	39		VW
96471776	25	125.5	37		DAWOO
压DAC306845	30	137	45		
XBGB40600S02(SNR)	42	—	37		FIAT
BAF-0126(SKF)	45/47	—	39		AUDI、VW
512106(BCA)	31.77	139	52		FORD
HUB055	28	122	47		MAZDA
512177	30	151.5	59		HONDA
HUB189-4 (L)		—			
HUB189-2 (R)		—		